

\* 별첨1

측정 결과

▶ 측정일 : 2018년 04월 02일

| 시료번호       | 측정 지점 | 측정 결과(f/cc) | 초과 여부 |
|------------|-------|-------------|-------|
| B-18040201 | 부지-1  | 0.001       | 기준미만  |
| B-18040202 | 부지-2  | 0.001       | 기준미만  |
| B-18040203 | 부지-3  | 0.000       | 기준미만  |
| B-18040204 | 부지-4  | 0.001       | 기준미만  |
| B-18040205 | 위생설비  | 0.001       | 기준미만  |
| B-18040206 | 음압기-1 | 0.004       | 기준미만  |
| B-18040207 | 음압기-2 | 0.002       | 기준미만  |
| B-18040208 | 음압기-3 | 0.001       | 기준미만  |
| B-18040209 | 음압기-4 | 0.001       | 기준미만  |
| B-18040210 | 음압기-5 | 0.002       | 기준미만  |

▶ 측정일 : 2018년 04월 03일


| 시료번호       | 측정 지점    | 측정 결과(f/cc) | 초과 여부 |
|------------|----------|-------------|-------|
| B-18040301 | 부지-1     | 0.001       | 기준미만  |
| B-18040302 | 부지-2     | 0.001       | 기준미만  |
| B-18040303 | 부지-3     | 0.001       | 기준미만  |
| B-18040304 | 부지-4     | 0.001       | 기준미만  |
| B-18040305 | 위생설비 - 1 | 0.001       | 기준미만  |
| B-18040306 | 위생설비 - 2 | 0.001       | 기준미만  |
| B-18040307 | 음압기-1    | 0.000       | 기준미만  |
| B-18040308 | 음압기-2    | 0.001       | 기준미만  |
| B-18040309 | 음압기-3    | 0.002       | 기준미만  |
| B-18040310 | 음압기-4    | 0.001       | 기준미만  |

▶ 측정일 : 2018년 04월 04일


| 시료번호       | 측정 지점  | 측정 결과(f/cc) | 초과 여부 |
|------------|--------|-------------|-------|
| B-18040401 | 폐기물반출구 | 0.002       | 기준미만  |

\* 별첨 2

측정지점위치

|                                                                                     |                                                                                                                                                                                             |
|-------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
|  | <div data-bbox="1329 1686 1465 2128"> <p>온수빌딩 2층</p> </div> <div data-bbox="1329 593 1465 1686"> <p>측정지점위치</p> </div> <div data-bbox="1329 183 1465 593"> <p>측정일 : 2018년 04월 02일</p> </div> |
|-------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|


## 추생지섬악지



측정일 : 2018년 04월 02일


\* 별첨 2

측정지점위치

|                                                                                     |                                                         |
|-------------------------------------------------------------------------------------|---------------------------------------------------------|
|  | <p>은수빌딩 4층</p> <p>측정지점위치</p> <p>측정일 : 2018년 04월 02일</p> |
|-------------------------------------------------------------------------------------|---------------------------------------------------------|


\* 별첨 2

측정지점위치

|                                                                                     |               |                            |
|-------------------------------------------------------------------------------------|---------------|----------------------------|
|  | <p>측정지점위치</p> | <p>측정일 : 2018년 04월 03일</p> |
| <p>은수빌딩 1층</p>                                                                      |               |                            |


\* 별첨 2

측정지점위치

|                                                                                     |  |  |        |  |                     |
|-------------------------------------------------------------------------------------|--|--|--------|--|---------------------|
|  |  |  | 측정지점위치 |  | 측정일 : 2018년 04월 03일 |
| 위생설비(은수빌딩 2층)                                                                       |  |  |        |  |                     |

\* 별첨 2


측정지점위치

|                                                                                     |                     |
|-------------------------------------------------------------------------------------|---------------------|
|                                                                                     | 측정일 : 2018년 04월 03일 |
|  | 측정지점위치              |
| 은수빌딩 5층                                                                             |                     |




\* 별첨 2

측정지점위치

|                                                                                     |        |  |                     |  |
|-------------------------------------------------------------------------------------|--------|--|---------------------|--|
|  |        |  | 측정일 : 2018년 04월 03일 |  |
| 은수빌딩 옥탑층                                                                            | 측정지점위치 |  |                     |  |

\* 별첨 2

측정지점위치

|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                            |        |                     |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------|---------------------|
| <div style="text-align: center;"> <p>주차장</p>  <p>The diagram shows a rectangular parking lot layout. On the left side, there is a staircase labeled 'DN' with an upward arrow. To the right of the staircase is a large rectangular area labeled '공영2'. Further right is a smaller rectangular area labeled '미용실' (beauty salon) with horizontal lines. To the right of the beauty salon is another large rectangular area labeled '공영1'. A small rectangular box labeled '폐기물반출구' (waste collection exit) is located between the '미용실' and '공영1' areas. Arrows indicate the flow from the staircase area towards the '공영2' and '공영1' areas.</p> </div> |        |                     |
| 폐기물반출 (은수빌딩 1층)                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                            | 측정지점위치 | 측정일 : 2018년 04월 04일 |